

\Palmer Civil Construction\FQM CRUSHING

DT 02 - Bell B50D		Unit #:	DT 02	Serial #:	AEBA750DE07004174
2012 Bell B50-D		Tag #:		Engine	Mercedes
		Hours	8,790.4	Engine Type	OM 502 LA
Date	Hours	Maintenance Performed	Assigned To	Total Cost	
13/09/2021	8,714	Transmission Wiring Harness replacement		\$934.09	
26/06/2020	7,784.8	4000 HR Service		\$0.00	
16/09/2021	8,248	Bell B 50D 250Hr Service	Wolfenden, Brad	\$0.00	
7/10/2021	8,520.7	A + R IDL light stuck on, A + R Left arm rest broken, A + R Left side mirror missing, A + R Reverse camera not working		\$0.00	
21/11/2020	8,531.1	Replace rear diff bearings, Repalce hyd pump drive shaft, 02 - A+R Pre Cleaner bowl, 01 - A+R airleak		\$3,175.50	
15/12/2021	8,495	Bell B50D 500Hr Service	Wolfenden, Brad	\$0.00	
4/05/2021	8,714	2 x Batteries		\$336.60	
11/10/2021	8,714	Hitachi fitter to diagnose and fix DT02, Mark Ward	Green, Lachlan	\$0.00	
11/10/2021	8,714	Transmission oil 40lt	Wolfenden, Brad	\$0.00	
25/08/2021	8,714	Replace Transmission Harness	Mostert, Neil	\$552.75	
TOTAL		Cost Per Mi/Km/Hr:	\$5.38	\$4,998.94	