

EX 10 - Caterpillar 320D LRR

Caterpillar 320D LRR

Unit #: EX 10

Tag #:

Hours 6,255

Serial #: CAT0320DCHJC00135

Custom 1 9kg Fire Ex new @ C

Custom 2 SOLD 1/11/22

| Date | Hours | Maintenance Performed | Assigned To | Total Cost |
|--------------|---------|---|---------------|--------------------|
| 26/09/2018 | 4,385 | Repair Worn Track Link | | \$366.30 |
| 20/10/2018 | 4,420.1 | R + R Hydraulic Hose assemblies @ Q/Hitch | | \$338.21 |
| 12/01/2019 | 4,420.1 | Replace tilt bucket hose, R+R Final Drive issue | | \$4,375.36 |
| 23/03/2019 | 4,385 | 320D 250Hr Service | | \$355.15 |
| 24/06/2020 | 4,493 | R/H front light inop | | \$7.86 |
| 17/05/2019 | 4,685 | R+R Hydraulic hose assembly (bucket) | | \$226.30 |
| 17/05/2019 | 4,753 | 320D 250Hr Service | | \$855.45 |
| 6/06/2019 | 4,786 | R+R Cutting edge | | \$389.11 |
| 7/06/2019 | 4,786 | Replace expired Fire Extinguisher with new unit | | \$180.12 |
| 14/11/2019 | 4,882 | 01 - Attend site at Martagallup Rd, install emergency master pin and rejoin track | | \$867.79 |
| 22/12/2020 | 5,665 | 01 - A+R tracks (FT 1736 7/11/19), 02 - gps bucket not working (FT 1745 19/11/19), 03 - pin has no holding pin (FT 1750 26/11/19) | | \$559.90 |
| 13/12/2019 | 5,005 | 320D 1000Hr Service, 320D 250Hr Service, 320D 500Hr Service | | \$525.80 |
| 8/01/2020 | 5,021 | 01 - A+R Q/Fill breather hose, 02 - Press out, clean up and refit track pin, 03 - replace missing Track bolts / nuts | | \$1,210.00 |
| 22/12/2020 | 5,021 | 01 - Panel and Paint turret, 02 - A+R Scratches on counter weight (Moved from WO#2597) | | \$60.50 |
| 26/05/2020 | 5,021 | 01 - Grease plant as required, 02 - Tighten A/C belt , 03 - Repairs to window slide mechanism, 04 - Top-up engine oil as found with extremely low oil level, 05 - A+R front wipers inop (MS 0701 30/01/20), 06 - A+R E-Stop | | \$291.37 |
| 27/02/2020 | 5,175 | 01 - A+R track pin walked out | | \$242.00 |
| 1/04/2020 | 5,245 | 320D 250Hr Service | | \$368.04 |
| 21/05/2020 | 5,245 | 04 - R+R No first aid kit (Garry 27/03/20) , 03 - A+R Grab Hydraulics damaged after Pre start (TM 12/03/20 0720) , 02 - A+R Fire Unit in Red (TH 11/03/20 0719) , 01 - A+R No horn (TH 11/03/20 0719), 05 - A+R top lock mechanism not holding locked (G... | | \$484.00 |
| 24/06/2020 | 5,340 | 03 - R+R switch panel broken | | \$119.82 |
| 22/12/2020 | 5,665 | 01 - R+R Teeth and retainers GP Bucket, 02 - A + R Rear spotties no go (James 27/2/20 0714), 03 - A + R Belt queaks when engine is reved up (Shane 29/05/2020 7701) | | \$242.00 |
| 26/05/2020 | 5,340 | Fit Tricoast mulching head and test | | \$513.23 |
| 12/05/2021 | 6,255 | 320D 250Hr Check over | | \$191.60 |
| 22/12/2020 | 5,665 | Fit GPS gear, Fit caps to auxillary lines, Fit SWL stickers, Supply fuel cap lock | | \$265.79 |
| 6/10/2020 | 5,492 | 320D 500Hr Service | | \$242.00 |
| 6/07/2021 | 5,970 | 320D 1000Hr Service, 320D 2000HR Service, 320D 500Hr Service | | \$333.78 |
| TOTAL | | Cost Per Mi/Km/Hr: | \$7.28 | \$13,611.49 |