

LO 11 - 2012 Caterpillar 980K

2012 Caterpillar 980K

Unit #: LO 11

Tag #:

Hours 13,311

Serial #: CAT0980KTCGTZ00344

Custom 1 SOLD 1/11/22

Custom 2

Date	Hours	Maintenance Performed	Assigned To	Total Cost
7/11/2018	10,459	Repair/Straighten LHS Step, Repair LH Mud Flap, Repair Bonnet Shroud, Refill Auto greaser, Install Fire Extinguisher, Adjust LH Arm Rest Cable		\$2,504.48
31/01/2019	10,459	Repairs to bonnet frame as required, Remove fule tank and repair crack, Re-Align Bonnet , R+R blown hydraulic hose, R+R Fire extinguisher, Install Missing Grill, Identify & Repair Oil Leak From Transmission, Identify & Repair Coolant Leak (WP Tel...		\$5,160.39
18/02/2019	10,459	Install plant ID decals		\$96.25
8/04/2019	10,698.1	980K 250Hr Service		\$782.13
24/06/2019	10,769.6	Bucket Repairs as required, Install Bucket Corner Protector, 04 - Install mud guard braces, 03 - Inspect and Rectify engine oil leak, 02 - Fab/Install 2-way hand peice plate, 01 - Repair Greaseline, 05 - R+R Battery isolator box latch, 06 - Paint...		\$2,836.44
10/06/2019	10,769.6	Conduct Routine 6 monthly Service to Fire Equipment - June 19		\$8.25
9/08/2019	10,769.6	01 - remove guards and prep for paint, 02 - Paint Guards and re-install to plant		\$1,742.77
17/09/2019	10,802.6	01 - R+R R/H lift cylinder hydraulic hoses		\$1,401.16
22/06/2020	10,846	01 - Install E-Stops and Isolator as required, 02 - Install Minespec decals, 03 - Install 9Kg Fire Extinguisher, 04 - Carry out Pre-Hire plant inspection with images to compliment report., 05 - Wash down plant as required		\$0.00
24/02/2022	13,304.3	efit Bucket with new bucket pin seals, Bucket needs new floor plate welding on, Bent steps and battery box cover need repairing	Ramen, Hansley	\$81.55
15/02/2020	10,846	01 - Attend site @ Old Boundary Rd - A+R Steering issue		\$12,529.96
8/04/2020	10,846	01 - A+R Steering Issue		\$755.19
22/05/2020	11,501	03 - A+R coolant is low (J 22/4/20 5613), 01 - A + R Auto Grease Disabled (J.V 5608 14/04/20), 02 - A+R aircon needs Looking at		\$0.00
30/04/2020	11,501	980K 500Hr Service, 980K 250Hr Service		\$520.74
22/05/2020	11,501	01 - A+R leak at hydraulic valve bank, 02 - A+R fan inop, 03 - Replace damaged section of 6mm HP grease line		\$2,585.21
19/03/2020	11,501	01 - R+R Bucket Edges		\$1,902.56
25/06/2020	11,501	980K 1000Hr Service		\$0.00
24/10/2021	13,304	980K 500Hr Service, 980K 250Hr Service, 980K 1000Hr Service	Wolfenden, Brad	\$231.33
15/07/2020	11,632	Replace fume disposal filter, 02 - A+R radiator latch , 01 - A+R grease lines (tash 5632 2/7/20)		\$153.23
28/07/2020	11,740	980K 250Hr Service		\$121.97
30/07/2020	11,750.6	02 - A+R windscreen washer , 01 - bucket needs re skining on the bottem		\$77.20
13/08/2020	11,875.2	01 - A+R dead batterys		\$935.00
10/09/2020	11,893.6	A + R DPF fault @ Tamarine		\$906.40
22/09/2020	11,921.1	980K 2000Hr Service		\$701.35
4/12/2020	12,153	01 - repair mud flaps		\$254.10
5/12/2020	12,153	01 - replace door window		\$176.00
2/06/2021	12,238	980K 500Hr Service		\$68.90
28/03/2022	13,304.3	R + R LH IOWER DOOR WINDOW, R + R Centre back window	Novus Windscreens	\$1,247.28
21/04/2021	12,245	R & R Door Latch on Loader		\$189.16
26/07/2021	12,245	Lachlan Ordered		\$140.61
25/05/2021	12,245	Replace reservoir on auto greaser		\$232.56

23/03/2023 10:01:59 AM

Date	Hours	Maintenance Performed	Assigned To	Total Cost
25/05/2021	12,245	Replace fuel cap 357-7399		\$187.29
25/05/2021	12,245	Seat cover heavy duty		\$169.40
2/06/2021	12,245	Replace wear plates		\$969.94
5/07/2021	12,245	Repair kick out switch		\$0.00
TOTAL		Cost Per Mi/Km/Hr:	\$13.94	\$39,668.80