

**LO 12 - Caterpillar 980K**

2014 Caterpillar 980K

Unit #: LO 12

Tag #:

Hours 10,652

Serial #: GTZ00795

Engine SOLD 1/11/22

Engine Type

Date	Hours	Maintenance Performed	Assigned To	Total Cost
11/07/2019	7,008	install missing air cleaner cover, R+R engine oil dipstick gauge, R+R damaged grease lines, R+R all four batteries, R+R Windscreen, R+R Cabin door gas strut, R+R A/C dryer assembly, R + R heel plates, R + R Tilt cylinder return hose, Install shims...		\$8,679.59
4/12/2019	7,317.2	01 - Installation of front wiper motor and pantograph assembly		\$158.75
29/12/2019	7,387	01 - Inspect Autolube system + repair lines and system as required, 02 - Shim Bucket Pivot and Tilt pins, 03 - Rectify + Adjust park brake, 04 - Replace cracked LH window, 05 - Remove cab + replace oring on Implement Pump outlet, 06 - Rectify Airc...		\$4,440.90
4/12/2019	7,387	01 - Remove compressor and install repair kit		\$715.24
4/12/2019	7,387	01 - Attend site @ Kuch Rd, A + R array of EC comms faults		\$4,407.04
8/11/2019	7,439.6	980K 500Hr Service, 980K 250Hr Service		\$181.50
4/12/2019	7,479.1	01 - Cracks in bucket-near heel plates on both sides (WB 3610 24/10/19), 04 - oil leak above diff (WB 3612 26/10/19), 02 - egr pressure fault (WB 3610 24/10/19), 03 - asses belts due to squealing (WB 3611 25/10/19), 05 - replace missing 9kg extin...		\$235.78
4/12/2019	7,540.7	05 - f/lh park light , 01 - replace service sticker 7750hr, 02 - A+R bucket cutting edge, 03 - fuel water seperator (WB 3618 4/11/19), 04 - needs new hydrolic breather filter		\$70.78
4/12/2019	7,540.7	01 - fire supression inop (WB 3617 2/11/19), 02 - rear tyres worn (WB 3617 2/11/19)		\$13,774.20
4/12/2019	7,549	01 - Repairs to bonnet latch		\$400.10
4/12/2019	7,611.9	02 - A+R intermittent auto-lube (greasing) issue, 01 - A+R starting fault, 03 - General checkover plant - advise any issues		\$181.50
4/12/2019	7,611.9	01 - Remove greasing unit and send away for inspection		\$60.50
5/12/2019	7,611.9	08 - A+R seat deflating (WK 3646 01/2/20), 07 - Get fittings to block off grease lines @ auto greaser (MK 04/12/19), 06 - A+R why the hydraulic's is over full - (MK 04/12/19), 05 - Need new hydraulic breather elment (Moved from WO# 2454), 04 - Re...		\$13,104.24
14/11/2019	7,639.7	01 - ride control not working(JB 3633 7/12/19)		\$121.00
15/12/2019	7,639.7	01 - Paint counter weight and rims		\$181.50
2/03/2020	7,679.1	02 - C/Out grease hose, 01 R+R Px switch @ grease pot		\$176.09
5/02/2020	7,679.1	01 - Fabricate tow pin @ 50ø x 200mm L		\$121.00
26/03/2020	8,464.2	01 - R+R Cutting edges, 02 - supply seat cover		\$2,056.56
25/06/2020	8,464.2	01 - Various repairs at FQM site		\$430.01
29/10/2020	8,464	980K 250Hr Service, 980K 500Hr Service, 980K 1000Hr Service		\$0.00
13/07/2020	8,823.5	02 - A+R cracked bucket, 01 - A+R R/H bonnet panel loose (GC 3093 10/7/20), - A+R grease lines		\$396.91
24/07/2020	8,834.3	01 - Calibration of load scale, 02 - A+R Hydraulic leak at Main Valve bank		\$2,998.71
11/08/2020	8,895.3	01 - hyd leak under cab		\$17.58
16/09/2020	8,895.3	Replace fuel cap, 04 - A+R Water fuel sensor, 03 - A+R EGR (Out of calibration), 02 - A+R A/C, 01 - Repair coolant leak		\$219.31
5/10/2020	9,000	980K 1000Hr Service		\$363.00
5/12/2020	9,143	Repair seat, 01 - repair mud flaps		\$254.10
25/01/2021	9,230	980K 500Hr Service, 980K 250Hr Service		\$0.00

Date	Hours	Maintenance Performed	Assigned To	Total Cost
2/02/2021	9,230	Replace rear window, Replace LH mirror		\$504.16
30/05/2021	9,230	R & R to LO 12 P 2149	Wolfenden, Brad	\$38.38
5/04/2022	10,636	R + R New Bucket Floor	Thomas, Brett	\$1,487.26
30/11/2021	10,584.1	Repairs to LO12	Evans, Todd	\$1,097.05
<b>TOTAL</b>			<b>Cost Per Mi/Km/Hr:</b>	<b>\$15.68</b>
				<b>\$56,872.76</b>