

DZ 08 - 2005 Caterpillar D10 R

2005 Caterpillar D10 R

Unit #: DZ 08

Tag #: 39,657

Hours

Serial #: AKT00564

Engine Caterpillar

Engine Type 3412E

Date	Hours	Maintenance Performed	Assigned To	Total Cost
25/08/2018	34,548	Weed and Seed, Spiral Guard Worn Ripper Hoses, Spiral Guard Light Wiring, Retighten GET bolt, Reroute Wiring to T/C sensor, Replace leaking Intercooler fan hose, Replace Wiper Module, Replace Wiper Arm, Replace Vimms Screen, Replace Striped Wiper ...		\$30,442.66
7/11/2018	34,548	D10 R 500Hr Service, CRC Door Hinges, Detail Cab + Wash Dozer, Install Am/Fm Speakers, Install Roof Lining, Paint Exhaust Stack - Mat Black, Remove and Replace Tilt Cylinder Protector Plate, Replace Hi Vis tape around ROPS, Replace Ripper Boot, Ro...		\$3,094.85
2/01/2019	34,548	Assess and Rectify Engine making oil, R+R Pressure Sensor (Air)		\$9,024.61
10/06/2019	35,009	D10 R 500Hr Service, D10 R 250Hr Service, D10 R 1000Hr Service, Complete Machine Off Hire from SPG		\$10,291.17
10/06/2019	35,009	Re-Seal Blad lift cylinders, CTS and SOS sampling by Westrac		\$4,396.23
10/06/2019	35,009	Drain and re-fill cooling system flowing bad SOS sample		\$740.66
24/06/2019	35,250	01 - Replace worn rippertyne pin, Supply Joystick assy' to site for installation (Tom Price BGC)		\$497.79
13/01/2020	35,250	01 - Supply of Parts to on-hire plant at BGC Tom Price - August 2019		\$16,221.28
10/03/2020	36,244	Off hire repairs as required - MAKE NUMERICAL LIST AND ITEMISE, 12 - R+R Front Window, 11 - R+R IDraft Arm trunnion bearings, 10 - Re-seal sump, 09 - R+R Ripper cylinder hoses, 08 - Remove cores to facilitate fan r+r, 07 - Replace radiator hose as...		\$26,663.49
10/03/2020	36,244	17 - Repairs to front housing after catastrophic yoke failure, 16 - A+R Few lights not working (P.T 1/04/20 4622) , 15 - A+R battery isolator Wear , 14 - A+R E Stop in cab not working (P.T 4618 28/03/200, 13 - A+R No service sticker (W.R 8/03/20 ...		\$4,116.87
22/06/2020	37,335	01 - A+R Leaking cooler core		\$935.91
25/06/2020	37,335	D10 R 1000Hr Service, D10 R 2000Hr Service, D10 R 250Hr Service, D10 R 500Hr Service		\$0.00
24/04/2020	37,335	01 - Get tracks repaired		\$24,817.43
29/07/2020	37,732	09 - Fan cover missing (JM 6818 11/7/20), 08 - A+R roofing falling off (JM 6817 10/7/20), 07 - R/H pivot shaft seal is leaking(JM 6817 10/7/20), 06 - A+R blade lift rams leaking (JM 6817 10/7/20), 05 - both draft arm hand rails snapped off (JM ...		\$892.38
1/08/2020	37,739	D10 R 500Hr Service		\$0.00
29/07/2020	37,859	D10 R 250Hr Service		\$181.50
24/08/2020	37,859	D10 R 2000Hr Service, D10 R 1000Hr Service		\$757.70
2/09/2020	37,898	01 - snapped track and cannon repairs		\$15,339.71
8/10/2020	37,949	01 - A+R aircon		\$478.25
24/08/2020	37,949	02 - A+R left tilt cylinder hoses, 01 - A+R door handle		\$633.78
16/12/2020	37,949	Replace roof liner, 01 - Replace fan motor @ A/C unit, Repair trans elec faults		\$1,512.68
8/10/2020	37,949	Replace missing drive sprocket bolt		\$103.36
18/01/2021	38,094	R + R Starter Motor, General inspection	Albany Autospark	\$110.00
21/02/2021	38,542	Complete off hire inspection, 01 - radiator repair (maca)		\$1,127.74
11/01/2021	38,542	D10 R 250Hr Service, D10 R 500Hr Service		\$0.00
15/02/2021	38,542	01 - Front main seal repair		\$865.71

Date	Hours	Maintenance Performed	Assigned To	Total Cost
16/06/2021	38,542	Replacement 5 keys for DZ 08		\$22.84
4/05/2021	38,542	R & R Steel Hydraulic Line on dozer 08		\$792.41
2/06/2021	38,542	Replace Corner Cutting Edge Tip Left side		\$1,363.42
3/08/2021	38,542	Assess DZ 08 faults & travel	Westrac Equipment	\$3,217.16
16/06/2021	38,542	Repair dozer		\$1,116.50
11/10/2021	38,542	Safety gumboots size 10 for chalky, Radiator Stop Leak	Wolfenden, Brad	\$0.00
23/07/2021	39,559	D10 R 500Hr Service	Wolfenden, Brad	\$1,125.26
25/08/2021	39,559	Supply & fit AM/FM radio	Mostert, Neil	\$374.00
14/09/2021	39,559	Electrical Issue	Hinchy's Auto Elecs	\$0.00
TOTAL		Cost Per Mi/Km/Hr:	\$32.18	\$161,257.33