

**EX 07 - Komatsu PC 138US-8**

2013 Komatsu PC 138US-8

Unit #: EX 07  
Tag #: A69138  
Hours: 4,665Serial #: KMTPC189C01030814  
Custom 1: READ NOTES SEC  
Custom 2: SOLD 1/11/22

Date	Hours	Maintenance Performed	Assigned To	Total Cost
15/11/2018	3,426	A + R UHF inop, A + R small oil leaks, A+ R Belt squeal, Assess E-stop damage (cracked), R + R broken / damaged mirrors, replace guard from blade cylinder (SE 0509 08/11/18)		\$172.96
15/11/2018	3,452	Additional works performed during / after service, PC138-8 USLC 250Hr Service, PC138-8 USLC 500Hr Service		\$555.24
5/03/2019	3,473	PC138-8 USLC 500Hr Service, PC138-8 USLC 250Hr Service		\$285.91
30/11/2018	3,489	Repair Worn tilt bucket, Machining - Materials and labour		\$3,947.92
5/03/2019	3,574	R+R Radiator Recovery Cap, R+R A/C belt, Check track tension and condition, Boom hose bracket cracked away, Blow our Radiator and condensor		\$583.24
10/07/2019	3,590	A+R Beacon inop (DM 0579 17/04/19), A+R Top headlight inop (DM 0579 17/04/19), AM/FM radio inop (DM 0579 17/04/19), Replace teeth with Rock Penetration Points, UHF Radio inoperative (BK 11/03/19), assess and determine if WS crack requires acti...		\$341.99
31/03/2020	4,341	replace damaged/broken mirror on handrail, missing cup holder behind seat (JMon 3256 6/11/19), Repair damaged handrails		\$0.00
13/03/2019	3,691	PC138-8 USLC 250Hr Service		\$288.43
24/01/2020	3,745	DAMAGE REPAIR - Repair large scratch to counterweight		\$0.00
15/05/2019	3,745	Attend site @ Broomehill - R+R broken alternator Belt		\$306.94
24/01/2020	3,838	02 - DAMAGE REPAIRS - Camera frame bent (DM 3204 10/07/19), 04 - DAMAGE REPAIRS - replace broken mirrors, 01 - DAMAGE REPAIRS - front top Headlights broken (DM 3204 10/07/19), 03 - DAMAGE REPAIRS - Hydraulic compartment door bent (DM 3204 10/07/19)		\$80.42
24/01/2020	4,320	R+R broken grease nipple at tilt bucket, 01 - batter bucket needs edges changing		\$90.75
22/06/2019	3,892	01 - Hydraulic Q/C fittings leaking		\$121.00
19/09/2019	3,926	01 - A/C inop (NH 3221 15/08/19)		\$60.50
2/10/2019	4,003	PC138-8 USLC 1000Hr Service, PC138-8 USLC 2000Hr Service, PC138-8 USLC 250Hr Service, PC138-8 USLC 500Hr Service		\$770.52
24/01/2020	4,052	01 - Attend site @ NASHS, A+R issue with UHF transceiver, 02 - needs fire ext (JM 3255 5/11/19)		\$363.00
25/02/2020	4,340	PC138-8 USLC 250Hr Service		\$302.50
9/01/2020	4,243	01 - Attend site @ Nashs. A + R issue with hydraulic block and sheared bolt		\$181.50
17/01/2020	4,315	02 - fuel guage not accurate (TH 1005 18/1/20), 01 - A+R cause of engine overheating		\$60.50
28/02/2020	4,319	01 - Remove, clean and re-fit frozen track pins as required		\$759.00
19/08/2021	4,581	Both wipers bent, No oil dipstick, Radio N/W	Palmer, Dave	\$55.40
22/06/2020	4,341	02 - A + R ydraulic hose leaking to tilt bucket (28/05/20), 01 - A + R Air con not working (28/05/20 8735)		\$225.50
14/06/2020	4,403	A + R Beacon not working, 03 - A+R T/L mirror (JM 8111 12/06/2020), 02 - A+R belts (GB 8112 12/06-2020), 01 - Change-out Bucket teeth in trenching bucket		\$1,081.06
13/05/2021	4,588	Replace Dipstick		\$55.40
<b>TOTAL</b>		<b>Cost Per Mi/Km/Hr:</b>	<b>\$9.20</b>	<b>\$10,689.68</b>