

LO 02 - 2012 Komatsu WA 320-6 PZ

2012 Komatsu WA 320-6 PZ

Unit #: LO 02
 Tag #: A67320
 Hours: 6,734

Serial #: KMTWA108J01071504
 Custom 1: SOLD 1/11/22
 Custom 2:

Date	Hours	Maintenance Performed	Assigned To	Total Cost
20/11/2018	4,034	A+R L/H Work light (EM 1644 7/11/18), A+R R/H worklight inop (EM 645 08/11/18), Assess condition of cutting edge reported as "worn" (EM 1645 08/11/18), R+R R/H mirror Glass broken (EM 1644 07/11/18), R+R wiper blades		\$403.18
10/06/2019	4,092	Assess soot reported around turbo (JM 26/09/18 1614), A+R top front light inop (DM 1637 27/10), A+R reported "clunk" in second gear (DM 19/09/18 1611)		\$45.79
20/11/2018	4,230	Additional Repairs Carried out during / after service, WA320-6 250Hr Service		\$154.01
10/06/2019	4,275	coolant leak (AH 3602 3/3/19), Wash out + Grease up Q/Hitch, Rear mirror missing (EM 1/12/18 1654), LH + RH mirrors missing (EM 04/12/18 1657), Adjust steering height control, A+R rear light blown (AH 3611 15/03/19), A+R bent step (EM 1657 04/12...)		\$302.50
25/02/2019	4,408	R+R Cutting edges		\$979.53
17/05/2019	4,482.5	Pre-Work Inspection		\$346.50
12/06/2019	4,510	WA320-6 250Hr Service , WA320-6 500HR Service		\$489.91
9/08/2019	4,510	DAMAGE REPAIRS - Rear L/H guard bent (NH 3622 08/06/19)		\$0.00
12/02/2020	4,832	01 - Exhaust leak @ turbo (GW 3644 12/08/19), 02 - jack shaft badly worn (gw 3669 2/10/19), 03 - seat bushes (gw 3669 2/1/19), 04 - fire ext missing (GW 3671 7/10/19)		\$332.75
18/11/2019	4,655	01 - Breakdwn, attend site @ Islet Rd A+R engine 'missing' and knocking.		\$7,876.58
27/11/2019	4,665.5	01 - Attend site @ Martagallup Rd - R+R engine oil and engine oil filter		\$794.64
15/01/2020	4,714.2	01 - reverse alarm inop (JM 368125/11/19)		\$0.00
23/06/2020	4,769	01 - A+R bushes and pins (GW 3689 5/12/19)		\$121.00
1/09/2020	5,094.4	01 - Carry out general check of plant after prolonged away-time		\$363.00
23/06/2020	0	01 - A+R hydraulic issue		\$181.50
8/06/2020	4,920	01 - Repair tyre - slow leak		\$60.00
5/06/2020	4,946	WA320-6 1000Hr Service, WA320-6 250Hr Check over, WA320-6 500HR Service		\$481.89
1/09/2020	5,092	A + R No horn (SL 1155 5/7/20)		\$10.28
27/08/2020	5,092	Repair tyre off bead		\$316.80
2/09/2020	5,094.4	01 - Clean out and regrease locking pins		\$121.00
13/10/2020	5,094.4	Replace cutting edges		\$1,172.16
11/03/2021	5,094.4	Replace U/S tyre		\$1,870.00
11/03/2021	5,094.4	Replace exhaust pipe after muffler, Replace crowd cylinder drop valve seals, Replace blown hoses		\$1,180.11
11/03/2021	5,094.4	Replace beacon, Repair auto greaser unit		\$225.50
29/10/2021	6,495	WA320-6 1000Hr Service, WA320-6 250Hr Check over, WA320-6 500HR Service	Wolfenden, Brad	\$297.00
22/07/2021	6,045	WA320-6 2000Hr Service	Wolfenden, Brad	\$1,346.71
11/12/2020	5,513	WA320-6 250Hr Check over, WA320-6 500HR Service		\$511.72
3/03/2021	5,513	Repair Hydraulic Hose		\$170.88
8/04/2021	5,513	R + R Front driveshaft inner and outer spline, Replace cutting edge, R + r Hydraulic Hose	Albany Engineering Co	\$645.19
17/03/2022	6,662	Replace Window, R + R Hydraulic Hoses	Novus Windscreens	\$637.12
13/05/2021	5,671	Replace heel plates		\$381.06
13/05/2021	5,671	Replace lock assembly		\$227.26
20/05/2021	5,671	1 x hydraulic steering hose to be made up		\$0.00

Date	Hours	Maintenance Performed	Assigned To	Total Cost
2/06/2021	5,671	Replace Bucket Dump Cylinder Hose		\$374.53
22/06/2021	5,671	Replace water pump part number 6754-61-1211		\$0.00
TOTAL		Cost Per Mi/Km/Hr:	\$3.37	\$22,420.12
GRAND TOTAL				\$447,092.51