

LO 08 - 2014 Komatsu WA 480-6

2014 Komatsu WA 480-6

Unit #: LO 08
 Tag #:
 Hours 13,176

Serial #: 91172
 Custom 1 SOLD 1/11/22
 Custom 2

Date	Hours	Maintenance Performed	Assigned To	Total Cost
9/11/2018	3,354.6	Requires Grease pot replenishing, Inspect gas struts on RH inspection door. Replace as required		\$152.62
19/09/2018	3,245.9	Replace Rear Spotting Mirror (Missing)		\$40.98
9/11/2018	3,354.6	Assess windsceen crack and advise if R+R required		\$61.05
9/11/2018	3,354.6	R + R Beacon with LED unit		\$291.50
27/08/2018	3,131.9	Attend site and install second hand loader tyre		\$858.44
22/01/2019	3,476	WA480-6 500Hr Service, WA480-6 250HR Service, Re-filled auto greaser		\$612.39
9/11/2018	3,250	WA480-6 250HR Service		\$59.31
9/11/2018	3,354.6	Engine power reported to be sluggish		\$128.62
10/07/2019	3,382.4	A+R headlight inop (side not specified) (CA 0740 20/11/18), A/C Inop (JB 0745 20/12/18), Assess chip / crack in windshield - advise severity and whether R+R is required (CA 0740 20/11/18), Hose leaking, RH Step requires straightening (CH 22/01/1...		\$1,885.42
19/09/2019	3,708.6	01 - Assess windscreen crack - photo required, 02 - A+R R/H bonnet gas strut (JB 03/07/19 2314), 03 - Repair Lime rust damage		\$1,498.00
23/03/2019	3,582	R+R Engine Air Primary Filter		\$38.66
11/07/2019	3,650	Pre-Work Inspection		\$0.00
23/04/2020	4,243	Replace damaged steer relief pressure sensor, Replace front trans output shaft seals, WA480-6 250HR Service, WA480-6 2000Hr Service		\$2,139.58
11/10/2021	8,001.3	500 Hour service	Wolfenden, Brad	\$173.89
11/10/2021	8,001.3	500 Hour service	Wolfenden, Brad	\$62.00
20/01/2021	3,740.9	01 - DAMAGE REPAIRS cracked windsreen (DS 2126 12/6/19), 02 - DAMAGE REPAIRS - R/H Door handle knob smashed (JV 7929 17/03/20)		\$0.00
17/11/2021	12,534.9	250 Hr Service, WA480-6 250HR Check over, WA480-6 500Hr Service	Wolfenden, Brad	\$467.05
9/11/2021	4,194.7	01 - Attend site @ Wilcox Rd, A + R Auto lube system fault, 02 - A+R seat needs repair or replacement (W.B 9/4/20 7939), 03 - A + R No horn (22/5/20 8734), 04 - A+R Brakes Shuddering (22/5/20 8734)		\$401.50
1/07/2020	4,243	WA480-6 2000Hr Service, WA480-6 1000Hr Service, WA480-6 250HR Check over, WA480-6 500Hr Service		\$1,042.39
19/09/2022	13,158	R + R Battery		\$0.00
10/12/2020	4,243	Replace cutting edges		\$1,609.06
9/11/2021	4,684.8	01 - A+R Low beam Globe blown, Replace seat		\$4,262.50
31/10/2020	4,684.8	WA480-6 500Hr Service, WA480-6 1000Hr Service		\$172.10
6/02/2021	5,861	WA480-6 2000Hr Service		\$6,860.95
9/02/2021	6,687.1	Replace Rear Tyres		\$7,656.00
4/02/2021	5,970	WA480-6 250HR Check over, WA480-6 500Hr Service, WA480-6 1000Hr Service		\$221.49
4/02/2021	5,970	WA480-6 250HR Check over, WA480-6 500Hr Service, WA480-6 1000Hr Service		\$224.62
4/02/2021	5,970	WA480-6 250HR Check over, WA480-6 500Hr Service, WA480-6 1000Hr Service		\$107.20
16/02/2021	6,687.1	WA480-6 500Hr Service		\$0.00
11/02/2021	6,687.1	Repair washers		\$328.61
6/02/2021	6,687.1	WA480-6 500Hr Service		\$206.20
8/04/2021	6,687.1	WA480-6 500Hr Service		\$906.53
21/04/2021	8,001.3	250 Hr Service		\$526.64
27/05/2021	8,001.3	Lachlan Ordered		\$1,628.00

Date	Hours	Maintenance Performed	Assigned To	Total Cost
26/05/2021	8,001.3	heel plates, bolts, nuts, washers		\$363.77
26/05/2021	8,001.3	Replace wiper motor at front		\$876.47
2/06/2021	8,001.3	Replace right side armrest, Repair steering column adjustment mechanism		\$688.67
12/10/2021	8,001.3	R + R Arm Bushes and seals, R + R F/R Switch	Ramen, Hansley	\$3,297.67
9/11/2021	12,168	WA480-6 2000Hr Service, WA480-6 250HR Check over, WA480-6 500Hr Service, WA500-7 1000Hr Service	Wolfenden, Brad	\$757.69
14/02/2022	13,026	Bucket Bushes, Repairs to Bucket, WA480-6 250HR Check over, WA480-6 500Hr Service, WA500-7 1000Hr Service	Ramen, Hansley	\$107.20
TOTAL		Cost Per Mi/Km/Hr:	\$4.06	\$40,714.76