

Make/Model: Kubota / RTV900

Description: 4WD Diesel Utility Vehicle, Hydraulic Tipping Body

Lot: 0059 **Serial:** 61278

Year: **Hours:** 1645 **Odometer:**

- ★☆☆☆☆ 1 Problem: Needs attention/repair to work as expected
- ★★☆☆☆ 1 Imperfection: Will need attention in near future
- ★★★☆☆ 3 Imperfection: May need Attention
- ★★★★☆ 24 Acceptable: As expected for age & type of item
- ★★★★★ 0 Acceptable: Free of Visible Wear



General

Overall Condition ★★★★★

Functional Test

Starts	Yes	
Steering		★★★★☆
Transmission		★★★★☆
Stall test		★★★★☆
Brakes		★★★★☆
Park Brake		★★★★☆
Electrics		★★★☆☆

Operator Area

Cleanliness		★★★★☆
Seat Condition		★★★☆☆
Switches		★★★☆☆
Gauges		★★★★☆
Wiper		★★★★☆
Mirrors	Yes	

Exterior

Paint Condition		★★★★☆
Steps & Handrails		★★★★☆
Bumpers		★★★★☆
Lights	Rear lights damaged on both sides	★☆☆☆☆

Engine

Fuel Type	Diesel	
Smoke Levels		★★★★☆
Noise Levels		★★★★☆
Exhaust Condition		★★★★☆
Belts Condition		★★★☆☆
Cooling System		★★★★☆

Drive Train

Gearbox		★★★★☆
Transmission		★★★★☆
Noises		

Hydraulics

Hoses & Lines		★★★★☆
---------------	--	-------

Wheels

Tyre Brand	MAG OFFROAD	
No. of Wheels	4	
Rims Condition		★★★★☆
Front LHS Tyre Condition	65 %	★★★★☆
Front RHS Tyre Condition	65 %	★★★★☆
Rear LHS Tyre Condition	65 %	★★★★☆
Rear RHS Tyre Condition	65 %	★★★★☆

Safety Features

Horn	Yes
------	-----