

Make/Model: Mack / GU713

Description: 6x4 Tandem Axle Dumptruck c/w 10.8L 6 Cylinder Mack MP7-395C Engine, Eaton Fuller 8LL 8 Speed Transmission, Swing Arm Tarp, Dual Wheels, A/C (Being

Lot: 0102 **Serial:** 1M2AX04C9CM012676

Year: 2012 **Hours:** **Odometer:**

- ★☆☆☆☆ 0 Problem: Needs attention/repair to work as expected
- ★★☆☆☆ 1 Imperfection: Will need attention in near future
- ★★★☆☆ 4 Imperfection: May need Attention
- ★★★★☆ 3 Acceptable: As expected for age & type of item
- ★★★★★ 0 Acceptable: Free of Visible Wear



General

Overall Condition ★★☆☆☆

Functional Test

Starts	Yes
Drives Forward	Yes
Drives Back	Yes
Drives Right	Yes
Drives Left	Yes
Brake Pedal Functions	Yes
Park Brake	Yes

Operator Area

Cleanliness	★★★★★
Seat Condition	★★★☆☆
Air Conditioning	Yes
Reverse Camera	No
Floor Mat	Yes
Mirrors	Yes Driver side mirror cracked
Windows	★★★☆☆

Exterior

Paint Condition	Paint chipped off on driver door, rust on dump bed	★★★☆☆
Overall Condition		★★★☆☆

Engine

Engine Make	Mack
Engine Model	MP7
Fuel Type	Diesel
Smoke Levels	★★★★★
Noise Levels	★★★★★

Transmission

Transmission Eaton Fuller 8LL 8 Speed

Body Type

Body Type Dump bed