

Body Type

Inspection Report

Make/Model: Kenworth / T800

Description: Tri Axle Dumptruck c/w 15L Cummins ISX 400 Diesel

Engine, Manual Transmission, Mid Lift Axle, Swing Arm Tarp, Tail Door, Dual Wheels, A/C (237,879 Miles) (Being

Lot: **Serial:** 1NKDX4TX99J256947

Year: 2009 **Hours:** 14469 **Odometer:** 237879 miles

**** 0 Problem: Needs attention/repair to work as expected ****

0 Imperfection: Will need attention in near future

3 Imperfection: May need Attention

2 Acceptable: As expected for age & type of item

4 Acceptable: Free of Visible Wear



General		
Overall Condition		****
	Functional Test	
Starts	Yes	
Drives Forward	Yes	
Drives Back	Yes	
Drives Right	Yes	
Drives Left	Yes	
Brake Pedal Functions	Yes	
Park Brake	Yes	
	Operator Area	
Cleanliness		****
Seat Condition		****
Air Conditioning	Yes	
Reverse Camera	No	
Floor Mat	No	
Mirrors	Yes	
Windows		****
	Exterior	
Paint Condition		****
Lights		****
Overall Condition	Cracked bonnet, concrete on chassis, rust on dump bed	***
	Engine	
Engine Make	Cummins	
Engine Model	ISX 400	
Fuel Type	Diesel	
Smoke Levels		****
Noise Levels		****
	Transmission	
Transmission	Manual	
	Body Type	

Dump Bed