

Created on	WO no	Priority	Status	Object ID	Trading	Object name	Work description	counter
1/mei/22	4416	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	bucket cylinder hose broken	14220
26/mei/22	5350	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	hose broken	14424
23/mei/22	5211	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	500 hr maintenance 349D	14936
27/mei/22	5520	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	ideler crackt needs welding	16390
1/jun/22	5767	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	BOTTOM CABIN GLASS BROKEN	14845
3/jun/22	5810	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	REPLACED FAN BELT	14845
18/jun/22	6714	Urgent	Technically te	T04309	ETR-1081	349D CATERPILL	REPLACE OIL COOLER GASKET	15048
19/jun/22	6770	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	1000 hr maintenance 349D	15463
23/jun/22	6962	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	REPLACE SENSOR/LIQUID LEVE	15048
23/jun/22	6961	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	REPLACED DAMAGED TOGGLE	15048
25/jun/22	7019	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	REPLACE INDICATOR AS AIR FIL	16075
5/jul/22	7667	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	replace horn	15570
5/jul/22	7668	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	REPLACE BROKEN UPPER WIND	16075
15/jul/22	8440	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	500 hr maintenance 349D	16075
25/jun/22	7018	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	REPLACE BROKEN TRACK SHO	15791
11/aug/22	10131	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	Replace leaking bucked cylinder	15905
10/aug/22	10080	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	Replace wornout ac fan motor	16044
11/aug/22	10174	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	2000 hr maintenance 349D	16762
20/aug/22	10641	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	CHANGE WORN GREASE VALVE	16193
2/sep/22	11657	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	repair worn undercarriage	16818
6/sep/22	11941	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	remove-stuck-rh-idler-for-ispection	16390
9/sep/22	12190	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	Replace-worn-starter-motor	16762
12/sep/22	12309	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	500 hr maintenance 349D	16506
26/sep/22	13733	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	replace radiator cap and flush syste	16762
1/okt/22	14154	Urgent	Administrativ	T04309	ETR-1081	349D CATERPILL	replace cylinder head gasket	16762
26/okt/22	16775	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	prepare machine ready for work	16818
25/okt/22	16597	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	sand blast and paint panels	16818
11/nov/22	18227	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	prepare machine to go to site	17256
1/dec/22	19938	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	1000 hr maintenance 349D	17109
6/dec/22	20390	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	Cab door completely rusted and se	18029
26/dec/22	22422	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	500 hr maintenance 349D	17493
30/dec/22	22648	Low	Administrativ	T04309	ETR-1081	349D CATERPILL	Top up engine oil	17493
31/dec/22	22945	Low	Administrativ	T04309	ETR-1081	349D CATERPILL	replace leaking engine to oil cooler	17537
8/jan/23	23364	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	replace broken shut off valve on en	17687
8/jan/23	23362	Low	Administrativ	T04309	ETR-1081	349D CATERPILL	replace missing track bolts /tighten	17727
29/jan/23	25010	Breakdown	Administrativ	T04309	ETR-1081	349D CATERPILL	Replace broken alternator belt and	17886
31/jan/23	25340	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	Replace leaking hyd switch	18029
1/feb/23	25394	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	2000 hr maintenance 349D	18029
14/feb/23	26564	Breakdown	Administrativ	T04309	ETR-1081	349D CATERPILL	Refit bucket cylinder top pin and fit	18064
20/feb/23	27217	Breakdown	Administrativ	T04309	ETR-1081	349D CATERPILL	REPLACE BROKEN TRACK BOLT	18080
7/mrt/23	28690	Breakdown	Administrativ	T04309	ETR-1081	349D CATERPILL	Repair hyd leak on bucket cylinder	18246
18/mrt/23	30020	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	500 hr maintenance 349D	18454
20/mrt/23	30265	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	Change leaking bucket cylinder ori	18454
25/mrt/23	30688	Breakdown	Administrativ	T04309	ETR-1081	349D CATERPILL	replace leaking sensor	18819
28/mrt/23	31054	Low	Administrativ	T04309	ETR-1081	349D CATERPILL	HANSAFLEXreplace hyd hoses bo	19615
6/apr/23	32031	Low	Administrativ	T04309	ETR-1081	349D CATERPILL	repair damaged door hyd pump sid	18893
7/apr/23	32080	Breakdown	Administrativ	T04309	ETR-1081	349D CATERPILL	repair hyd leak	18819
12/apr/23	32521	Low	Administrativ	T04309	ETR-1081	349D CATERPILL	repair ac fan blower	18893
13/apr/23	32558	Low	Administrativ	T04309	ETR-1081	349D CATERPILL	fit missing track plate bolts	18946
18/apr/23	33154	Low	Administrativ	T04309	ETR-1081	349D CATERPILL	Main pump door repair	19687
26/apr/23	34019	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	1000 hr maintenance 349D	19054
10/mei/23	35558	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	Replace missing track shoe and bo	19132
1/jun/23	38182	Normal	Administrativ	T04309	ETR-1081	349D CATERPILL	Change faulty batteries	19379

3/jun/23	38426	Normal	Administrative	T04309	ETR-1081	349D CATERPILL	500 hr maintenance 349D	19479
10/jun/23	39128	Breakdown	Administrative	T04309	ETR-1081	349D CATERPILL	Replace faulty ac compressor	19566
23/jun/23	40943	Breakdown	Technically te	T04309	ETR-1081	349D CATERPILL	replace leaking final drive hose	19760
25/jun/23	41066	Breakdown	Technically te	T04309	ETR-1081	349D CATERPILL	replace 12v batteries 70amp	19760
2/jul/23	42098	Normal	Technically te	T04309	ETR-1081	349D CATERPILL	replace fire extinguisher	19930
8/jul/23	42794	Normal	Technically te	T04309	ETR-1081	349D CATERPILL	2000 hr maintenance 349D	19984
23/aug/23	49447	Low	Technically te	T04309	ETR-1081	349D CATERPILL	OIL SAMPLE	19930
11/okt/23	56386	Low	Technically te	T04309	ETR-1081	349D CATERPILL	OIL SAMPLE	20467
11/aug/23	47709	Normal	Technically te	T04309	ETR-1081	349D CATERPILL	500 hr maintenance 349D	20467
9/sep/23	51644	Normal	Technically te	T04309	ETR-1081	349D CATERPILL	1000 hr maintenance 349D	20971
28/sep/23	54596	Breakdown	Technically te	T04309	ETR-1081	349D CATERPILL	hose leak from 5h30 to 9h30	21400
30/sep/23	54991	Normal	Technically te	T04309	ETR-1081	349D CATERPILL	500 hr maintenance 349D	21478
4/okt/23	55631	Low	Technically te	T04309	ETR-1081	349D CATERPILL	replace lights	21537
11/okt/23	56382	Breakdown	Technically te	T04309	ETR-1081	349D CATERPILL	repair ac system	21587
15/okt/23	57139	Breakdown	Technically te	T04309	ETR-1081	349D CATERPILL	Change oring on hyd hose at valve	21589
1/nov/23	60138	Normal	Technically te	T04309	ETR-1081	349D CATERPILL	2000 hr maintenance 349D	22043

Sign off	Service order	Created date	Sign off date	Unit	Description	Counter
Yes	SO0000015	4/07/2017 11:17	13/08/2017 16:03	E598	CHANGE RETAINER AND TEETH	828
Yes	SO0000621	7/12/2017 15:08	7/12/2017 15:12	E598	500 HRS. SERVICE-NMDC	1500
Yes	SO0000493	21/11/2017 8:55	11/02/2018 15:02	E598	CHANGE WINDOW (NMDC MALD)	1969
Yes	SO0001012	1/03/2018 15:32	1/03/2018 15:34	E598	CHANGE FUEL FILTERS	2467
Yes	SO0001013	1/03/2018 15:36	1/03/2018 15:39	E598	500 HRS. SERVICE	2506
Yes	SO0001065	30/03/2018 11:02	30/03/2018 11:05	E598	1000 HRS. SERVICE	2960
Yes	SO0001219	9/05/2018 16:06	9/05/2018 16:13	E598	500 HRS SERICE-NMDC	3496
Yes	SO0002142	11/09/2018 16:46	11/09/2018 16:46	E598	ADJUST TRACKS	3837
Yes	SO0001957	5/09/2018 14:43	5/09/2018 14:43	E598	ONE TRACK PIN COMING OUT	3918
Yes	SO0001958	5/09/2018 14:44	5/09/2018 14:45	E598	REMOVE ROCK PLACING BUCKET-FIX K198	3925
Yes	SO0001959	5/09/2018 14:46	5/09/2018 14:53	E598	2000 HRS SERVICE+ CHNAGE BUCKET K198 TO K075	3988
Yes	SO0001960	5/09/2018 14:54	5/09/2018 14:55	E598	CHANGE BUCKET K075 TO K198+TRACK TENSION+WELDING	3999
Yes	SO0006311	24/09/2018 17:18	1/12/2018 17:42	E598	PREPARATION FOR 5063 GEWAN ISLAND LONG REACH CO	4140
Yes	SO0007037	12/03/2019 9:10	17/03/2019 10:10	E598	500 HRS SERVICE	4453
Yes	SO0007453	3/07/2019 18:18	3/07/2019 18:20	E598	BUCKET REPAIR	4642
Yes	SO0007556	8/08/2019 14:46	8/09/2019 17:01	E598	PREPARATION FOR HAIL & GASHA	4925
Yes	SO0007082	6/04/2020 8:42	6/04/2020 8:43	E598	REPLACE BATTERY	5025
Yes	SO0007083	6/04/2020 8:45	6/04/2020 8:53	E598	RESEAL BOOM CYLINDER LH/RH	5025
Yes	SO0007085	6/04/2020 8:56	6/04/2020 9:04	E598	UNDERCARRIAGE REPAIR	5025
Yes	SO0007087	6/04/2020 9:11	6/04/2020 9:16	E598	1000 HRS SERVICE	5029
Yes	SO0007256	30/04/2020 23:32	30/04/2020 23:33	E598	CHANGE SEAL FL	5030
Yes	SO0007722	18/06/2020 10:25	18/06/2020 10:26	E598	REPAIR HEADLIGHT/GREASING	5053
Yes	SO0007954	5/07/2020 14:58	5/07/2020 15:00	E598	TOPUP ENGINE OIL	5115
Yes	SO0007955	5/07/2020 15:01	5/07/2020 15:02	E598	HYDRAULIC HOSE REPAIR	5182
Yes	SO0007956	5/07/2020 15:03	5/07/2020 15:04	E598	FIX COOLANT TEMPERATURE SENSOR	5256
Yes	SO0007957	5/07/2020 15:06	5/07/2020 15:07	E598	BUCKET REPAIR	5306
Yes	SO0008115	20/07/2020 15:44	20/07/2020 15:45	E598	TOPUP ENGINE OIL	5346
Yes	SO0008116	20/07/2020 15:46	20/07/2020 15:46	E598	FIX GREASE HOSE	5451
Yes	SO0008117	20/07/2020 15:47	20/07/2020 15:48	E598	TOPUP ENGINE OIL	5469
Yes	SO0008118	20/07/2020 15:48	20/07/2020 15:55	E598	500 HRS SERVICE	5510
Yes	SO0008119	20/07/2020 15:57	20/07/2020 15:58	E598	FIX BUCKET CYLINDER PIPE CLAMP	5519
Yes	SO0008368	9/08/2020 11:13	9/08/2020 11:19	E598	FINAL DRIVE OIL CHANGE/TOPUP ENGINE OIL	5681
Yes	SO0008369	9/08/2020 11:20	9/08/2020 11:23	E598	WELDING CRACK ON BOOM/GREASING	5799
Yes	SO0008458	13/08/2020 14:20	13/08/2020 14:21	E598	TOPUP ENGINE OIL & COOLANT	5867
Yes	SO0008459	13/08/2020 14:23	13/08/2020 14:24	E598	CHANGE BUCKET; ROCK TO SAND BUCKET	5973
Yes	SO0008537	18/08/2020 13:19	18/08/2020 13:27	E598	2000 HRS SERVICE	6013
Yes	SO0008538	18/08/2020 13:34	18/08/2020 13:35	E598	TOPUP ENGINE OIL/GREASING	6088
Yes	SO0008665	29/08/2020 11:19	29/08/2020 11:20	E598	BUCKET & BOOM CRACK REPAIR	6145
Yes	SO0008666	29/08/2020 11:21	29/08/2020 11:24	E598	TOPUP ENGINE OIL/GREASING	6160
Yes	SO0008667	29/08/2020 11:25	29/08/2020 11:30	E598	STICK CYLINDER GREASE HOSE BROKEN	6218
Yes	SO0008843	8/09/2020 15:34	8/09/2020 15:38	E598	TOPUP ENGINE OIL/GREASING	6312
Yes	SO0008844	8/09/2020 15:39	8/09/2020 15:42	E598	TRAVEL MOTOR HOSE BROKEN	6425
Yes	SO0008870	16/09/2020 13:14	16/09/2020 13:16	E598	TOPUP ENGINE & TRANSMISSION OIL/GREASING	6459
Yes	SO0008871	16/09/2020 13:17	16/09/2020 14:41	E598	500 HRS SERVICE	6499
Yes	SO0009191	5/10/2020 7:23	5/10/2020 7:25	E598	CHANGE BUCKET (K438 TO K292)	6532
Yes	SO0009017	27/09/2020 14:37	27/09/2020 14:57	E598	TOPUP ENGINE OIL/GREASING	6552
Yes	SO0009192	5/10/2020 7:26	5/10/2020 7:28	E598	REPAIR CRACK ON BOOM/BUCKET LOCK BOLT TIGHTING/GF	6568
Yes	SO0009193	5/10/2020 7:29	5/10/2020 7:31	E598	TOPUP ENGINE OIL/GREASING	6866
Yes	SO0009263	6/10/2020 15:15	6/10/2020 15:16	E598	REPAIR CRACK ON BOOM	6979
Yes	SO0009265	6/10/2020 15:16	28/10/2020 13:37	E598	1000 HRS SERVICE	6997
Yes	SO0009475	28/10/2020 13:43	28/10/2020 13:44	E598	REPAIR LIGHT & WIPER	7028
Yes	SO0009476	28/10/2020 13:45	28/10/2020 13:46	E598	CHANGE BUCKET (K292 TO K438)	7039
Yes	SO0009477	28/10/2020 13:47	28/10/2020 13:48	E598	CHANGE BUCKET (K438 TO K292)	7082
Yes	SO0009478	28/10/2020 13:49	28/10/2020 13:50	E598	TOPUP ENGINE OIL/GREASING	7112
Yes	SO0009479	28/10/2020 13:52	28/10/2020 13:53	E598	WELDING & PAINT CRACK ON BOOM	7120
Yes	SO0009480	28/10/2020 13:54	28/10/2020 14:01	E598	ADJUST LH TRACK/GREASING	7184
Yes	SO0009481	28/10/2020 14:05	28/10/2020 14:07	E598	TOPUP ENGINE OIL/GREASING	7194
Yes	SO0009482	28/10/2020 14:09	28/10/2020 14:10	E598	CHANGE BUCKET (K292 TO K438)	7428
Yes	SO0009685	8/11/2020 9:17	8/11/2020 9:19	E598	REPLACE PULLEY & BELT	7457
Yes	SO0009684	8/11/2020 9:16	8/11/2020 9:17	E598	CHANGE BUCKET (K438 TO K292)	7459
Yes	SO0009686	8/11/2020 9:20	8/11/2020 9:41	E598	500 HRS SERVICE	7512
Yes	SO0009687	8/11/2020 9:43	8/11/2020 9:44	E598	REPLACE HEAD LIGHT BULBS	7570
Yes	SO0010199	15/12/2020 15:09	15/12/2020 15:09	E598	WELDING CRACK ON BOOM	7878

Yes	SO0009971	29/11/2020 7:43	29/11/2020 7:45	E598	ENGINE OIL REFILL	7948
Yes	SO0010013	29/11/2020 14:08	9/12/2020 15:41	E598	2000 HRS SERVICE	7993
Yes	SO0010086	8/12/2020 8:34	8/12/2020 8:35	E598	CHANGED BUCKET K438 TO K292	8028
Yes	SO0010014	29/11/2020 14:17	29/11/2020 14:18	E598	CHANGE WATER SEPARATOR SENSOR	8067
Yes	SO0010647	6/01/2021 10:19	6/01/2021 10:20	E598	CHANGE BUCKET	8197
Yes	SO0010581	2/01/2021 10:18	2/01/2021 10:19	E598	FILL ENGINE OIL	8217
Yes	SO0010585	2/01/2021 10:33	2/01/2021 10:34	E598	FILL ENGINE OIL	8286
Yes	SO0010589	2/01/2021 10:55	2/01/2021 10:56	E598	FILL ENGINE OIL	8331
Yes	SO0010539	30/12/2020 11:18	30/12/2020 11:21	E598	TRACK LINK, IDLER ASSEMBLY REPAIR	8527
Yes	SO0010540	30/12/2020 11:22	30/12/2020 11:26	E598	500 HRS SERVICE	8527
Yes	SO0010543	30/12/2020 11:39	30/12/2020 11:40	E598	FILL ENGINE OIL	8555
Yes	SO0010593	2/01/2021 13:25	2/01/2021 13:25	E598	FILL ENGINE OIL	8668
Yes	SO0010899	1/02/2021 17:13	1/02/2021 17:18	E598	CHNAGE GREASE NIPPLES & RE-TAPPING	8723
Yes	SO0010901	2/02/2021 8:44	2/02/2021 8:45	E598	TOPUP ENGINE OIL	8756
Yes	SO0010902	2/02/2021 8:46	2/02/2021 8:47	E598	TOPUP ENGINE OIL	8770
Yes	SO0010903	2/02/2021 8:50	2/02/2021 8:52	E598	CHANGE BUCKET FROM K292 TO K438	8818
Yes	SO0010917	2/02/2021 9:41	2/02/2021 9:44	E598	TOPUP ENGINE OIL	8823
Yes	SO0011026	13/02/2021 16:56	13/02/2021 17:03	E598	1000 HRS SERVICE	8999
Yes	SO0011269	7/03/2021 16:15	7/03/2021 16:15	E598	REPLACE HOSES	9483
Yes	SO0011268	7/03/2021 16:23	7/03/2021 16:24	E598	500 HRS SERVICE	9506
Yes	SO0011435	15/03/2021 11:19	15/03/2021 11:20	E598	REPLACE STARTER MOTOR	9749
Yes	SO0011356	9/03/2021 16:45	10/04/2021 7:47	E598	REPLACE HYD HOSE; HYD PUMP TO CONTROL VALVE	9779
Yes	SO0011453	15/03/2021 14:21	15/03/2021 14:21	E598	HYDRAULIC LEAK	9865
Yes	SO0011589	28/03/2021 16:19	8/05/2021 15:11	E598	REFURBISH H-LINK & SIDE ARMS	10049
Yes	SO0011746	6/04/2021 9:51	6/04/2021 9:52	E598	WELDING BOOM & STICK	10049
Yes	SO0012221	18/05/2021 9:32	27/06/2021 14:35	E598	INSTALL NEW COOLER (OLD REMOVED & INSTALLED TO E62)	10049
Yes	SO0012875	6/07/2021 7:28	6/07/2021 7:29	E598	PO0012686 HYDRAULIC HOSE REPAIR	10049
Yes	SO0012966	15/07/2021 7:55	24/08/2021 14:16	E598	2000 HRS SERVICE	10058
Yes	SO0012970	15/07/2021 11:15	15/07/2021 11:15	E598	TIGHT TRACK PLATES ON RUNNING GEAR	10060
Yes	SO0013224	19/08/2021 14:26	22/08/2021 15:30	E598	CHANGE WIPER BLADE, LIGHTS AND PAINTING	10066
Yes	SO0013302	31/08/2021 10:41	31/08/2021 10:42	E598	HIGH PRESSURE HOSE AC MOTOR LEAKING	10071
Yes	SO0013408	19/09/2021 10:34	26/09/2021 14:32	E598	AC COMPRESSOR	10107
Yes	SO0013393	16/09/2021 13:20	16/09/2021 13:22	E598	TRACK BOLTS REPLACED	10308
Yes	SO0013457	25/09/2021 15:13	25/09/2021 15:14	E598	CYLINDER RESEAL	10425
Yes	SO0013613	17/10/2021 9:35	17/10/2021 9:36	E598	REPLACE TRACK ROLLERS	10669
Yes	SO0013722	1/11/2021 8:15	1/11/2021 8:17	E598	1000 HRS SERVICE	11053
Yes	SO0013777	9/11/2021 7:25	11/01/2022 17:26	E598	REPLACE BROKEN TEETH (K399)	11248
Yes	SO0013778	9/11/2021 7:31	27/11/2021 10:38	E598	UNDERCARRIAGE REPAIR; TRACK PLATES & ROLLERS LEAKIN	11282
Yes	SO0013710	31/10/2021 7:11	27/11/2021 10:30	E598	REPLACE WIPER MOTOR +CAMERA CABLE	11512
Yes	SO0013889	27/11/2021 10:34	27/11/2021 10:34	E598	500 HRS SERVICE	11512
Yes	SO0014005	12/12/2021 8:01	12/12/2021 8:01	E598	HORN NOT WORKING	11850
Yes	SO0014019	14/12/2021 9:23	14/12/2021 9:24	E598	2000 HRS SERVICE	11948
Yes	SO0014087	27/12/2021 14:43	27/12/2021 14:44	E598	PULLEY & BELT TENSIONER DAMAGED	12003
Yes	SO0014040	19/12/2021 13:37	4/01/2022 17:12	E598	TURBO OUTLET TUBE TO COOLER SEAL BROKEN	12056
Yes	SO0013923	29/11/2021 8:56	4/01/2022 17:15	E598	FRONT GLASS CRACKED	12299
Yes	SO0014262	8/02/2022 17:13	8/02/2022 17:13	E598	500 HRS SERVICE	12500
Yes	SO0014264	9/02/2022 15:52	9/02/2022 15:52	E598	1000 HRS SERVICE	12999
Yes	SO0014235	7/02/2022 14:05	21/02/2022 15:47	E598	REPLACE DEFECTIVE HORN	13000
Yes	SO0014193	30/01/2022 13:44	2/03/2022 15:22	E598	FRONT GLASS BROKEN	13118
Yes	SO0014409	22/03/2022 15:54	22/03/2022 15:54	E598	500 HRS SERVICE	13510